

CITY OF LOS ANGELES
CALIFORNIA

BOARD OF
BUILDING AND SAFETY
COMMISSIONERS

VAN AMBATIELOS
PRESIDENT

E. FELICIA BRANNON
VICE PRESIDENT

JOSELYN GEAGA-ROSENTHAL
GEORGE HOVAGUIMIAN
JAVIER NUNEZ



ERIC GARCETTI
MAYOR

DEPARTMENT OF
BUILDING AND SAFETY
201 NORTH FIGUEROA STREET
LOS ANGELES, CA 90012

FRANK M. BUSH
GENERAL MANAGER
SUPERINTENDENT OF BUILDING

OSAMA YOUNAN, P.E.
EXECUTIVE OFFICER

Simpson Strong-Tie
12246 Holly Street
Riverside, CA 92509

Attn: Tim Kaucher, P.E.
(800) 999-5099

RESEARCH REPORT: RR 25719
(CSI # 06 05 23)

BASED UPON ICC EVALUATION SERVICE
REPORT NO. ESR-2607

REEVALUATION DUE
DATE: August 1, 2019
Issued Date: July 1, 2017
Code: 2014 LABC

GENERAL APPROVAL – Reevaluation - Connectors for Panelized Roof Construction.

DETAILS

The above assemblies and/or products are approved when in compliance with the use, description, design, installation, conditions of use, and identification of Evaluation Report No-2607 reissued January 1, 2017 of the ICC-ES Evaluation Services, Incorporated, the report, in its entirety, is attached and made part of this general approval

The parts of Evaluation Report No. ESR-2607 marked by the asterisks are modified by the Los Angeles Building Department from this approval.

The approval is subject to the following conditions:

1. The connectors must be manufactured, identified and installed in accordance with this report and the manufacturer's published installation instructions. A copy of the instructions must be available at the job site at all times during installation.
2. Calculations showing compliance with this report must be submitted to the code official. The calculations must be prepared by a registered design professional where required by the statutes of the jurisdiction in which the project is to be constructed.
3. Adjustment factors noted in Section 4.1 and the applicable codes must be considered, where applicable.

RR25719
Page 1 of 2

Simpson Strong-Tie Co., Inc.

Re: Connectors for Panelized Roof Construction

4. Connected wood members and fasteners must comply respectively with Sections 3.7.2 and 3.7.3 of this report.
5. Use of fasteners with preservative treated or fire retardant treated lumber must be in accordance with Section 3.7.3 of this report.
6. The connectors must be manufactured, identified and installed in accordance with this report and the manufacturer's published installation instructions. A copy of the instructions must be available at the job site at all times during installation.
7. Welded connectors are manufactured under a quality control program with inspections by Benchmark Holdings L.L.C. (AA-660).

DISCUSSION

The report is in compliance with 2014 City of Los Angeles Building Code,

The approval is based on tests complying with AC 13.

This general approval will remain effective provided the Evaluation Report is maintained valid and unrevised with the issuing organization. Any revision to the report must be submitted to this Department for review with appropriate fee to continue the approval of the revised report.

Addressee to whom this Research Report is issued is responsible for providing copies of it, complete with any attachments indicated, to architects, engineers and builders using items approved herein in design or construction which must be approved by Department of Building and Safety Engineers and Inspectors.

This general approval of an equivalent alternate to the Code is only valid where an engineer and/or inspector of this Department has determined that all conditions of this Approval have been met in the project in which it is to be used.

QUAN NGHIEM, Chief
Engineering Research Section
201 N. Figueroa St., Room 880
Los Angeles, CA 90012
Phone- 213-202-9812
Fax- 213-202-9943

QN
RR25719
R06/23/2017
TLB1700238
2304.9.3

Attachments: ICC ES Evaluation Report No. ESR-2607 (9 Pages)